PICTURE 1

IBM Personal System/2 Enhanced 2.88MB Diskette Drive

August, 1992

This supplement contains a Symptom-to-FRU Index and a parts listing for the IBM Personal System/2 Enhanced $2.88 \, \mathrm{MB}$ Diskette Drive.

Insert this supplement in the IBM Personal System/2 ${\it Hardware\ Maintenance\ Service\ manual\ (part number\ 15F2200,\ form\ number\ SBOF-3988-00)}$.

IBM and Personal System/2 are trademarks of the International Business Machines Corporation. | Copyright International Business Machines Corporation 1992. All rights reserved.

Note to U.S. Government users-Documentation related to Restricted rights-Use, duplication, or disclosure is subject to restrictions set forth in GSA ADP Schedule Contract with IBM Corp.

Part Number 42G2346 Form Number S42G-2346-00

Enhanced 2.88MB Diskette Drive

1.0 Enhanced 2.88MB Diskette Drive

The Enhanced 2.88MB (MB = 1 000 000 bytes) Diskette Drive is a 3.5-inch drive with the following features:

Electrical diskette eject Security eject override Supports software eject commands Supports DOS, OS/2, and other operating systems

2.0 Security Mode Switch

The Security Mode Switch is located on the right, rear corner of the hard disk drive. The switch settings are as follows:

+--- Important ------+

- 1 Software eject and security eject override enabled
- 0 Software eject and security eject override disabled

Note: Some IBM computers do not support the Security Mode Switch
feature. On those computers, with the switch set to 1, the eject
override is permanently on and the user cannot insert or eject diskettes.

3.0 Symptom-to-FRU Index

Error symptoms and the FRUs that might be responsible for the failure are listed below. $\,$

Error / Symptom	FRU / Action
605 (Diskette Unlock)	Enhanced 2.88MB Diskette Drive System Board
668 (Security Option Failed)	Enhanced 2.88MB Diskette Drive System Board

Parts Listing

4.0 Parts Listing

Enhanced 2.88MB Diskette Drive with mounting hardware (for PS/2 Models 56/57)

92F0132

Printed in the U.S.A.