Addendum
(for SOYO-CD Revision 990201 All-in-One)

Among the drivers listed for your board on this CD are the INTEL Busmaster drivers for 95, NT and OS/2. These drivers are however not included on the CD.   Installing Busmaster drivers will enhance the performance of your harddisk, the drivers are however NOT important for the proper functioning of your system.

SOYO Speedpro

The CD does include the SOYO Speed PRO Busmaster driver, this driver can be installed under Windows 95/98 as replacement for the INTEL Busmaster drivers.

Download

The INTEL Busmaster drivers can be downloaded from our website at:
http://www.soyo.com.tw
Or from the INTEL website at:
http://developer.intel.com/design/chipsetsets/drivers