IMPORTANT UPDATE INFORMATION

The difference between the 810DTC mainboard and the 810DTA mainboard is only the onboard audio codec. The onboard audio codec on U7 of the 810DTA mainboard is "AD1881A", so the item 8 of the section 3.5 INSTALLATION OF DEVICE DRIVERS must be changed. Please refer to the following to install the correct audio device driver.

3.5 INSTALLATION OF DEVICE DRIVERS

8. Change the directory to "\Driver\mainboard\Intel\810\ad1881" and then choose the operation system to install the onboard audio device driver.

item 8 of the section 3.5 INSTALLATION OF DEVICE DRIVERS must be changed. Please refer to the following to install the correct audio device driver.

3.5 INSTALLATION OF DEVICE DRIVERS

8. Change the directory to "\Driver\mainboard\Intel\810\ad1881" and then choose the operation system to install the onboard audio device driver

DOC NO: UM-810DTC-L3

DOC NO: UM-810DTC-L3

IMPORTANT UPDATE INFORMATION

The difference between the 810DTC mainboard and the 810DTA mainboard is only the onboard audio codec. The onboard audio codec on U7 of the 810DTA mainboard is "AD1881A", so the