Second Ethernet Device Driver Important Note

Before you begin installation of your Ethernet adapter card:

 Make sure you have the correct model. The correct one is the Intel EtherExpress™ Flash32 Adapter (part number EILA-8225).

Please make sure you have not ordered EILA-8215. This product is not supported with this device driver.

- If you do not have the correct board, or if your board is defective or needs replacement, contact Intel customer support at **1-503-629-7000**.
- Once you have verified that you have the correct board, disregard the hardware installation instructions that shipped with it. Instead, follow the instructions in the *Intel EtherExpress Flash32 LAN Adapter for Indigo*^{2™} *Installation Guide*, which shipped with the Silicon Graphics, Inc., software device driver (part number SC4-EISAE++D-1.0).
 - For Silicon Graphics[®] support, call **1-800-800-4SGI**.
- 3. Please note that *only a single (1)* Intel EtherExpress Flash32 Adapter Card is supported in an Indigo² system.

Silicon Graphics is a registered trademark and E++ and $Indigo^2$ are trademarks of Silicon Graphics, Inc. EtherExpress is a trademark of Intel Corporation.